

# CLEANERS


Over 60 years of experience with cleaners and degreasers. **For safe, effective cleaning.**

## PROBLEM

Without cleaners and degreasers: Contaminants, soils and oils on components cause performance failures in production and plant operations.

## SOLUTION

With cleaners and degreasers: Cleaner components increase production quality, help to decrease operating costs, and maximise performance of LOCTITE® Adhesives.



# Clean parts, hands and **mechanical equipment**

LOCTITE® cleaners and degreasers provide highly effective water- and solvent-based cleaning of components, worktops, floors, parts and hands. The major factors to consider are drying time, residue, odour and substrate compatibility.



## How to choose the right cleaner.

### DEGREASING/PARTS CLEANING

For removing dirt, resins, metal filings, lacquer, oils and greases from components.

### HAND CLEANING

Available with and without abrasives for removing dirt, grease, grime, oil and adhesives from hands.



## Find the right product for your application



### Degreasers / Parts Cleaners

LOCTITE® SF 7070™

LOCTITE® SF 7063™

LOCTITE® SF 7840™

LOCTITE® SF 790™

LOCTITE® SF 7633™

LOCTITE® SF 7200™

### Hand Cleaners

LOCTITE® SF 7617™

LOCTITE® SF 7850™



## Degreasers & Parts Cleaners



**SF 7070™**  
ODC-Free

A non-aqueous, hydrocarbon-based solvent designed for cleaning and degreasing surfaces, as well as for general-purpose industrial cleaning. Safe on aluminium, rubber and most plastics, and will not cause flash rusting on water-sensitive parts.



**SF 7063™**  
Parts Cleaner

General purpose, non-CFC solvent based parts cleaner and degreaser for use prior to bonding and sealing applications. Dries fast and residue-free. Use to prepare surfaces prior to application of adhesive or sealant.



**SF 7840™**  
Water-based

Industrial strength, general purpose cleaner and degreaser. Contains no hazardous solvents, is biodegradable, non-flammable, non-toxic and cherry scented. Concentrated formula can be diluted with water.



**SF 790™**  
Gasket Remover

A gray to off-white methylene chloride liquid solvent in an aerosol spray designed to remove baked-on chemical gaskets, gasket cements and conventional gasket materials from metal surfaces. Its aerosol spray form enables spray application on to intricate shapes with maximum penetration.



**SF 7633™**  
Parts Cleaner

Non chlorinated parts cleaner formulated for removing oil, grease, fluids, oxidised oils (gum) and asphalt from metal parts including aluminium. Penetrates dirt and corrosion and flushes them away, eliminating the need to disassemble.



**SF 7200™**  
MC Free Gasket Remover

Methylene chloride free, solvent-based cleaner designed to remove cured chemical gaskets on metal flanges. Particularly suitable for aluminium or other soft metal flanges, where scraping could lead to surface damage. Will not run, even on vertical surfaces.

## Hand Cleaners



**SF 7617™**  
Wipes

Citrus-scented hand cleaning towels with a cleaning formula that is capable of removing tar, grease, wax, ink, paint, lubricants and adhesives.



**SF 7850™**  
Hand Cleaner

Citrus scented general purpose hand cleaner containing no petroleum solvents. It cleans with or without water and can remove ground-in dirt, grease, resin, inks, oils and stains whilst soothing and protecting hands.

## CLEANERS

Product	Item Number	Package Size	Drying Time	Residue/ Rinsability	Odour
DEGREASERS					
SF 7070™	88365	400 ml	Few hours depending on environment. Oily residue is slow drying. Wiping or blowers will accelerate dry time	No rinse. Oily residue dries slowly	Citrus
SF 7840™	2046049	709 ml	Equivalent to the evaporation rate of water. Wiping or blowers will accelerate dry time	Rinses residue-free with water	Cherry
	2046047	3.78 L			
	2046048	18.9 L			
PART CLEANERS					
SF 7063™	2098749	400 ml	< 60 secs	No rinse and no residue	Solvent
SF 7200™	2099006	400 ml	Does not dry. Allow 10 - 30 minutes to soften gaskets, then wipe or scrape clean	Oily residue	Solvent
SF 790™	135544	510 g	Does not dry. Allow 5 - 10 minutes to soften gaskets, then wipe or scrape clean	Oily residue	Solvent
SF 7633™	1506652	411 g	Does not dry. Allow 30 minutes to dwell, then wipe	No rinse and no residue	Solvent
HAND CLEANER					
SF 7617™	337637	75 wipes	1 to 5 mins	No rinse and no residue	Citrus
SF 7850™	366943	400 ml	1 to 5 mins	Liquid and abrasive residue. Wipe or rinse if desired	Citrus
	367218	4 L			

